



**QUEEN'S
UNIVERSITY
BELFAST**

Oxidation-induced Cu coating on steel surface

Li, N., & Sha, W. (2014). *Oxidation-induced Cu coating on steel surface*. Abstract from International Conference on Metallurgical Coatings and Thin Films, Session GP: Applications, Manufacturing, and Equipment, San Diego, United States. <http://www.materialstoday.com/metals-alloys/events/the-41st-international-conference-on-metallurgical/>

Queen's University Belfast - Research Portal:

[Link to publication record in Queen's University Belfast Research Portal](#)

Publisher rights

© 2014 The Authors

General rights

Copyright for the publications made accessible via the Queen's University Belfast Research Portal is retained by the author(s) and / or other copyright owners and it is a condition of accessing these publications that users recognise and abide by the legal requirements associated with these rights.

Take down policy

The Research Portal is Queen's institutional repository that provides access to Queen's research output. Every effort has been made to ensure that content in the Research Portal does not infringe any person's rights, or applicable UK laws. If you discover content in the Research Portal that you believe breaches copyright or violates any law, please contact openaccess@qub.ac.uk.

Oxidation-induced Cu coating on steel surface

Na Li¹, Wei Sha²

1. Laser Advanced Manufacturing Technology R & D Center, School of Materials and Metallurgy, University of Science and Technology Liaoning, Anshan, 114051, China
2. School of Planning, Architecture and Civil Engineering, Queen's University Belfast, Belfast, BT9 5AG, UK




Fig.1 Back scattered electron images of the cross sections of the steel samples with 6.8%Cu (a) and 12.6%Cu (b) after heating at 1000°C for 2h.




Fig.2 Optical microscope image of the inclined cross section of steel with 6.8%Cu after heating at 1150°C for 2h.




Fig.3 SEM morphology and EDX spectra of the substrate and Cu layer on the inclined cross section of steel with 6.8%Cu after heating at 1150°C for 2h.




Fig.4 Macro-photograph, SEM morphology and EDX spectra of the surface of the steel with 12.6% Cu after descaling.